

SAFETY DATA SHEET BARITE (ALL GRADES)

1 IDENTIFICATION OF THE SUBSTANCE/PREPARATION AND OF THE COMPANY/UNDERTAKING

PRODUCT NAME	BARITE (ALL GRADES)
APPLICATION	Weighting agent.
SUPPLIER	M-I SWACO. Holburn House, 475-485, Union Street, Aberdeen. AB11 6DB Scotland. UK T = +44 (0)1224-336336 F = +44 (0)1224-336351 E-mail = MBXMSDS-EH@miswaco.com
EMERGENCY TELEPHONE	(24 Hour) Europe +44 (0) 208 762 8322, Asia Pacific +65 633 44 177, China +86 10 5100 3039, Middle East and Africa +961 3 487 287.

2 HAZARDS IDENTIFICATION

Not regarded as a health or environmental hazard under current legislation.

HUMAN HEALTH

IARC Monographs, Vol 68, 1997, concludes that there is sufficient evidence that inhaled crystalline sillica in the form of quartz or crystobalite from occupational sources cause cancer in humans. IARC classification Group 1. Because of quantity and composition, the health hazard is small.

3 COMPOSITION/INFORMATION ON INGREDIENTS

Name	EC No.	CAS-No.	Content	Classification
BARITE (Ba(SO4))	236-664-5	13462-86-7	60-100%	-
QUARTZ, CRYSTALLINE SILICA	238-878-4	14808-60-7	5-10%	Xn;R20.

The Full Text for all R-Phrases are Displayed in Section 16

COMPOSITION COMMENTS

The data shown is in accordance with the latest EC Directives. Barite is a naturally occurring mineral. This product contains a small quantity of quartz, crystalline silica. Prolonged and repeated exposure to concentrations of crystalline silica exceeding the workplace exposure limit (WEL) may lead to chronic lung disease such as silicosis. Because of quantity and composition, the health hazard is small.

4 FIRST-AID MEASURES

INHALATION

Move the exposed person to fresh air at once. If respiratory problems, artificial respiration/oxygen. Get medical attention if any discomfort continues.

INGESTION

Immediately give a couple of glasses of water or milk, provided the victim is fully conscious. Get medical attention if any discomfort continues.

SKIN CONTACT

Remove contaminated clothing immediately and wash skin with soap and water. Get medical attention promptly if symptoms occur after washing.

EYE CONTACT

Make sure to remove any contact lenses from the eyes before rinsing. Promptly wash eyes with plenty of water while lifting the eye lids. Continue to rinse for at least 15 minutes. Get medical attention if any discomfort continues.

5 FIRE-FIGHTING MEASURES

EXTINGUISHING MEDIA

Use fire-extinguishing media appropriate for surrounding materials.

SPECIAL FIRE FIGHTING PROCEDURES

Containers close to fire should be removed immediately or cooled with water.

PROTECTIVE MEASURES IN FIRE

Self contained breathing apparatus and full protective clothing must be worn in case of fire.

6 ACCIDENTAL RELEASE MEASURES

PERSONAL PRECAUTIONS

Wear protective clothing as described in Section 8 of this safety data sheet.

ENVIRONMENTAL PRECAUTIONS

Do not allow to enter drains, sewers or watercourses.

SPILL CLEAN UP METHODS

Avoid generation and spreading of dust. Shovel into dry containers. Cover and move the containers. Flush the area with water.

7 HANDLING AND STORAGE

USAGE PRECAUTIONS

Avoid inhalation of dust and contact with skin and eyes.

STORAGE PRECAUTIONS

Store in tightly closed original container in a dry, cool and well-ventilated place.

8 EXPOSURE CONTROLS/PERSONAL PROTECTION

Name	Std	LT - ppm	LT - mg/m3	ST - ppm	ST - mg/m3
QUARTZ, CRYSTALLINE SILICA	WEL		0.1 mg/m3 resp.dust		

INGREDIENT COMMENTS

WEL = Workplace Exposure Limits

PROTECTIVE EQUIPMENT







ENGINEERING MEASURES

Provide adequate general and local exhaust ventilation.

RESPIRATORY EQUIPMENT

Respiratory protection must be used if air contamination exceeds acceptable level. Dust filter P3 (for especially fine dust/powder).

HAND PROTECTION

For prolonged or repeated skin contact use suitable protective gloves. Rubber or plastic.

EYE PROTECTION

Wear approved chemical safety goggles where eye exposure is reasonably probable.

OTHER PROTECTION

Wear appropriate clothing to prevent any possibility of skin contact. Provide eyewash station.

9 PHYSICAL AND CHEMICAL PROPERTIES

APPEARANCE	Powder, dust			
COLOUR	Tan to Grey			
ODOUR	Odourless or No characteristic odour.			
SOLUBILITY	Insoluble in water			
MELTING POINT (°C) BULK DENSITY	1580 1920 - 2400 kg/m3	RELATIVE DENSITY	4.2 - 4.25 20°C	

10 STABILITY AND REACTIVITY

STABILITY

Stable under normal temperature conditions and recommended use.

CONDITIONS TO AVOID

Avoid wet and humid conditions.

11 TOXICOLOGICAL INFORMATION

INHALATION

Dust in high concentrations may irritate the respiratory system.

INGESTION

May cause discomfort if swallowed.

SKIN CONTACT

Powder may cause mechanical irritation to skin.

EYE CONTACT

Particles in the eyes may cause irritation and smarting.

12 ECOLOGICAL INFORMATION

ECOTOXICITY

OSPAR have defined this chemical as PLONOR. Contact M-I Swaco's QHSE Department for ecological information. Barite is a naturally occurring mineral.

13 DISPOSAL CONSIDERATIONS

DISPOSAL METHODS

Recover and reclaim or recycle, if practical. Dispose of waste and residues in accordance with local authority requirements.

14 TRANSPORT INFORMATION GENERAL The product is not covered by international regulation on the transport of dangerous goods (IMDG, IATA, ADR/RID). 15 REGULATORY INFORMATION RISK PHRASES NC Not classified. SAFETY PHRASES NC Not classified.

UK REGULATORY REFERENCES

Chemicals (Hazard Information & Packaging) Regulations.

EU DIRECTIVES

REACH. With respect to minerals, Article 2 § 7(b) and Annex V point 7 explicitly exempt from registration and evaluation "minerals which occur in nature, if they are not chemically modified." This product is exempt from registration. Dangerous Substance Directive 67/548/EEC. Dangerous Preparations Directive 1999/45/EC. Regulation (EC) No 1907/2006 of the European Parliament and of the Council of 18 December 2006 concerning the Registration, Evaluation, Authorisation and Restriction of Chemicals (REACH), establishing a European Chemicals Agency, amending Directive 1999/45/EC and repealing Council Regulation (EC) No 793/93 and Commission Regulation (EC) No 1488/94 as well as Council Directive 76/769/EEC and Commission Directives 91/155/EEC, 93/67/EEC, 93/105/EC and 2000/21/EC, including amendments.

GUIDANCE NOTES

Workplace Exposure Limits EH40.

16 OTHER INFORMATION

GENERAL INFORMATION

HMIS Health - 1 HMIS Flammability - 0 HMIS Physical Hazard - 0 E - Safety glasses, Gloves, Dust Respirator

INFORMATION SOURCES

Product information provided by the commercial vendor(s). Material Safety Data Sheet, Misc. manufacturers. Micromedex. European Chemicals Bureau - ESIS (European Chemical Substances Information).

REVISION COMMENTS

General revision. Compiled or revised by Sandra McWilliam

REVISION DATE: 12-03-08

BARITE (ALL GRADES)

ISSUED BY Bill Cameron REVISION DATE 12-03-08 REV. NO./REPL. SDS GENE ATED 6 SDS NO. 11207 RISK PHRASES IN FULL NC Not Lastfied. R20 Harmut by inhalation.

DISCLAIMER

MSDS furnished independent of product sale. While every effort has been made to accurately describe this product, some of the data are obtained from sources beyond our direct supervision. We cannot make any assertions as to its reliability or completeness; therefore, user may rely only at user's risk. We have made no effort to censor or conceal deleterious aspects of this product. Since we cannot anticipate or control the conditions under which this information and product may be used, we make no guarantee that the precautions we have suggested will be adequate for all individuals and/or situations. It is the obligation of each user of this product to comply with the requirements of all applicable laws regarding use and disposal of this product. Additional information will be furnished upon request to assist the user; however, no warranty, either expressed or implied, nor liability of any nature with respect to this product or to the data herein is made or incurred hereunder.